

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: HOPKINSVILLE, CITY OF

Community No: 210055

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

### 1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	13-04-5407P	01/31/2014	WESTWOOD/BOXWOOD DRAINAGE PROJECT	21047C0244C	21047C0244D

### 2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	06-04-BR90A	08/03/2006	INDIAN HILLS, SECTION 1, BLOCK G, LOT 1 -- 309 APACHE DRIVE	2100550005B	21047C0332D
LOMA	09-04-0390A	12/04/2008	EAGLE'S COVE SUBDIV, SECTION 1, LOT 45 -- 757 CLAW COURT	21047C0353C	21047C0353D
LOMA	10-04-1864A	03/16/2010	1102 EAST 21ST STREET	21047C0353C	21047C0353D
LOMA	11-04-3342A	03/02/2011	WESTWOOD SUBDIVISION NO. 2, UNIT NO. 1, LOT 20 -- 116 BOXWOOD DRIVE	21047C0244C	21047C0244D
LOMA	11-04-4274A	03/29/2011	SOUTH FORK PLACE, UNIT 3, LOT 21A -- 374 MARTIN PLACE DRIVE	21047C0353C	21047C0353D
LOMA	12-04-3875A	05/03/2012	HUNTING CREEK SUBDIVISION, SECTION 2, LOT 100 -- 108 QUAIL RIDGE DRIVE	21047C0353C	21047C0353D
LOMA	14-04-1542A	12/24/2013	SKYLINE PARK REAL ESTATE DEVELOPMENT, LOT 115 -- 307 HILLAIRE DRIVE	21047C0353C	21047C0353D
LOMA	15-04-0724A	10/30/2014	OAKHURST SUBDIVISION, BLOCK 2, LOT 15 -- 901 HURST DRIVE	21047C0331C	21047C0331D

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: HOPKINSVILLE, CITY OF

Community No: 210055

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	15-04-3480A	02/26/2015	DIVISION NO. 2, RADZ LLC, CAMBRIDGE HEIGHTS, UNIT 3, LOT 11-A -- 610 ASHBURY CIRCLE	21047C0332C	21047C0332D
LOMA	15-04-4136A	03/23/2015	SIVLEY TRACT, SECTION 2, LOTS 73 & 74 -- SADDLEBROOK COURT	21047C0353C	21047C0353D
LOMA	16-04-1983A	01/21/2016	SIVLEY TRACE SECTION 2, LOT 75 -- SADDLEBROOK COURT	21047C0353C	21047C0353D
LOMA	07-04-6124A	10/09/2007	COX MILL ESTATES SECTION 7, LOT 12 -- 687 HURL WAY	2102770008B	21047C0334D
LOMA	12-04-0835A	11/18/2011	Lot 10, Skyline Park Real Estate Development Subdivision - 400 West Riverwood Drive	21047C0353C	21047C0353D

### 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	00-04-1910A	04/04/2000	513 DONNA COURT	4

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

### 4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		